Item 3: 540iA, 740iA/E32 and 840iA with EGS

| Hard shift from 1-2 under small load | EGS data version 2324 2425 2628 | Convert EGS control unit to data version 3232 by replacing the EPROM. EPROM part number 24 60 1 422 397 ECE |
|--------------------------------------|--|--|
| | 2028 | 24 60 1 422 397 ECE 24 60 1 422 399 Japan |

Item 4: 540iA, 740iA/E32 and 840iA with EGS

| EGS data version 2324 | Convert EGS control unit to data version 3232 by replacing the |
|-----------------------|--|
| 2425 | EPROM. EPROM part number |
| 2628 | 24 60 1 422 397 ECE |
| 2729 | 24 60 1 422 399 Japan |
| | 2324 2425 2628 |

Note:

This only applies in the case of vehicles with a transmission with serial number 18584 or lower. If the problem still exists after the EGS control unit has been replaced and after a sufficiently long adaptation test drive, the hydraulic control unit should also be replaced. Part no. 24 34 1 422 136

Complaint

Constraints and test conditions

Remedy

Item 5: 540iA, 740iA/E32 and 840iA with EGS

| A jolt when changing down 5-3 under load | EGS data version 2324 2425 2628 | Convert EGS control unit to data version 3232 by replacing the EPROM. EPROM part number 24 60 1 422 397 ECE |
|---|--|--|
| | 2729 | 24 60 1 422 399 Japan |

Item 6: 540iA, 740iA/E32 and 840iA with EGS

| The converter with lock up clutch judders when it cuts in at a speed of | EGS data version 2324 | Convert EGS control unit to data version 3232 by replacing the |
|---|--------------------------|--|
| approx. 85 km/h, or you can hear a | 2425 | EPROM. EPROM part number |
| droning noise at 85-100 km/h under | 2628 | 24 60 1 422 397 ECE |
| load when the converter with lock up clutch is closed | 2729 | 24 60 1 422 399 Japan |

Complaint

Constraints and test conditions

Remedy

Item 7: 540iA, 740iA/E32 and E38 as well as 840iA with EGS and AGS

| The vehicle takes more than 2 | | |
|---|--|--|
| seconds to react when moving the | | |
| gear selector from N to D or from N to R. | | |

Oil level OK Gear selector position OK Transmission with serial number 70967 or less

Both plain compression rings on the converter support shaft should be replaced with modified versions in accordance with the enclosed installation instructions

| | | Note:Modified plain compression rings have been fitted in series production as from transmission serial number 70968Parts required for each vehicle:2 x plain compression rings Part no. 24 23 1 422 387 1 x oil seal ring Part no. 24 31 1 421 583 14 x sealing rings Part no. 24 31 1 219 165 2 x oil seal rings Part no. 24 34 1 421 736 4 x oil seal rings Intake/pressure duct Part no. 24 34 1 421 145 |
|---|--|---|
| Complaint | Constraints and test conditions | Remedy |
| Item 8: 540iA with AGS from 09/93 - 11 | /94 | |
| Unexpected and hard shift 5-4 and 4- 5 under constant load. It takes less than a second to shift up or down | AGS control unit with data version 2626 | Convert the AGS control unit to data version 2929 by replacing the EPROM |
| | | Note: The control unit fitted in series production since 12/94 is OK. EPROM part number 24 60 1 422 562 ECE 24 60 1 422 564 Japan |
| Item 9: 740iA/E38 | | |
| Poor shifting in particular 2-3, 3-4 | AGS data version | Convert the AGS control unit to data |

| Poor shifting, in particular 2-3, 3-4 | AGS data version | Convert the AGS control unit to data |
|---------------------------------------|------------------|--------------------------------------|
| and 5-4 are hard | 2020 | version 2929 by replacing the |
| | 2424 | EPROM |
| | 2828 | EPROM part number |
| | | 24 60 1 422 560 |